

PROBLEM	PROBABLE CAUSE	SOLUTION
Glazing	<ol style="list-style-type: none"> 1. Too much ink. 2. Hard water. 3. Dampening solution too acid. 4. Glaze on rollers. 	<ol style="list-style-type: none"> 1. Modify ink/water mix in order to have less water. 2. Choose a softer water (deionized water). 3. Verify pH and conductivity and adjust, if necessary. 4. Clean rollers; replace, if necessary.