

TROUBLESHOOTING FOR SHEETFED PRESSES

GLOSS AND CHEMICAL GHOSTING : The printed image from the first side of a printed sheet can be seen in reverse on the second side printed.

CAUSES

1. Oxidizing ink.
2. Ink drying too quickly.

REMEDIES

1. Run heavier ink coverage side first. This avoids lighter coverage burning into facing, unprinted surface.
2. Avoid the addition of drying accelerants to inks and fountain solution.

